

1/18/97 -169892

Penn Center West

Building III, Suite 300

Pittsburgh, PA 15276

(412) 788-2717

FAX (412) 788-1316

15 July 1997

Mr. Michael McAteer
U.S. Environmental Protection Agency
Region V
77 West Jackson Boulevard
HSRW-6.I
Chicago, Illinois 60604-3590

Subject:

Enviro-Chem Superfund Site

Monthly Progress Report Number 47

June 15 through July 14, 1997

Dear Mr. McAteer:

Enclosed is the subject progress report Number 47. Copies of the reports have been submitted to Mr. Tony Likins at IDEM.

Sincerely,

Mark J. Dowiak, P.E.

Mach Danish

Project Manager

MJD:rz

Enclosure

cc:

Dr. Roy O. Ball, PhD., P.E. - ERM

Mr. Norman Bernstein, Esq. – N.W. Bernstein & Associates

Mr. John Kyle III, Esq. - Barnes & Thornburg



To:

Tony Likins, IDEM

Michael McAteer, U.S. EPA '

From:

Mark J. Dowiak M. Dav

Date:

15 July 1997

Subject:

Enviro-Chem Superfund Site

Monthly Progress Report Number 47

June 15 through July 14, 1997

This Monthly Progress has been prepared in accordance with Section XII of the Consent Decree entered September 10, 1991, Number 83-419C, U.S.D.C. District of Indiana.

MEMORANDUM

Activities

de maximis, inc. conducted the June monthly site inspection at the Enviro-Chem Superfund site on June 20, 1997. The following conditions were noted during the monthly site inspection:

- The distances from the lowest strand of barbed wire to the channel bottom in the north drainage ditch and the Parcel 45 south diversion channel were 27 inches and 22.5 inches, respectively. These are the same distances that were measured during the May inspection.
- The decon pad and the water storage pad contain water. This does not appear to be causing any effect on the site.
- The asphalt material that has been placed against the outside of the fence directly across from the Boone County Resource Recovery Systems (BCRRS) office which resulted in a two (2) to three (3) foot elevation increase continues to be monitored each month. There does not appear to be any significant effect on the fence as of this inspection.
- The areas where the sheens were observed in March were inspected. There were no visible signs of sheens observed during this inspection.
- The weeds in the ditches in the southern portion of the site were cut.

The Requests for Bids for construction of the remedial action were issued on June 16, 1997.



15 July 1997 Page 2

Activities to be Conducted from July 15 through August 14, 1997

- de maximis, inc. will conduct the July monthly site inspection.
- The Trustees will receive and review the bids for construction of the Revised Remedial Action Plan.

MJD:rz



Penn Center West Building III, Suite 300 Pittsburgh, PA 15276 (412) 788-2717 FAX (412) 788-1316

21 July 1997

Mr. Michael McAteer
U.S. Environmental Protection Agency
Region V
77 West Jackson Boulevard
HSRW-6J
Chicago, Illinois 60604-3590

Subject:

Enviro-Chem Superfund Site

Monthly Progress Report Number 47, Revision

June 15 through July 14, 1997

Dear Mr. McAteer:

Enclosed is the revised subject progress report Number 47. The date of the issuance of bids has been corrected. Copies of the reports have been submitted to Mr. Tony Likins at IDEM.

Sincerely.

Mark J. Dowiak, P.E.

Monte Danals

Project Manager

MJD:rz

Enclosure

cc: Dr. Roy O. Ball, PhD., P.E. – ERM

Mr. Norman Bernstein, Esq. – N.W. Bernstein & Associates

Mr. John Kyle III, Esq. - Barnes & Thornburg



To:

Tony Likins, IDEM

Michael McAteer, U.S. EPA

From:

Mark J. Dowiak M. Daub.

Date:

Subject:

Enviro-Chem Superfund Site

Monthly Progress Report Number 47, Revision

June 15 through July 14, 1997

This Monthly Progress has been prepared in accordance with Section XII of the Consent Decree entered September 10, 1991, Number 83-419C, U.S.D.C. District of Indiana.

MEMORANDUM

Activities

de maximis, inc. conducted the June monthly site inspection at the Enviro-Chem Superfund site on June 20, 1997. The following conditions were noted during the monthly site inspection:

- The distances from the lowest strand of barbed wire to the channel bottom in the north drainage ditch and the Parcel 45 south diversion channel were 27 inches and 22.5 inches, respectively. These are the same distances that were measured during the May inspection.
- The decon pad and the water storage pad contain water. This does not appear to be causing any effect on the site.
- The asphalt material that has been placed against the outside of the fence directly across from the Boone County Resource Recovery Systems (BCRRS) office which resulted in a two (2) to three (3) foot elevation increase continues to be monitored each month. There does not appear to be any significant effect on the fence as of this inspection.
- The areas where the sheens were observed in March were inspected. There were no visible signs of sheens observed during this inspection.
- The weeds in the ditches in the southern portion of the site were cut.

The Requests for Bids for construction of the remedial action were issued on June 13, 1997.



Activities to be Conducted from July 15 through August 14, 1997

- de maximis, inc. will conduct the July monthly site inspection.
- ► The Trustees will receive and review the bids for construction of the Revised Remedial Action Plan.

MJD:rz